

- Site Report -

Date: January 5, 2012

IRD Sales Order: 11167

To: Cindy Ireland From: Bryan Knight

Project Name/Location: LTPP AZ1 US93

Service Date(s): November 1 2011

Job Description: Site Check Maintenance Visit

Work Completed:

 Performed Electrical reading of Loops and Bending Plates. Found readings within normal specifications.

- Performed Electrical reading of the Solar Power output within normal specifications.
- Visual inspection of Solar Panels, Bending Plates, and Roadway shows no unusual wear and tear.
- Performed housekeeping of the Electronics Cabinet and Cabinet Filter.
- Site remains fully functional and operating normally.

6/19/96 IRD FORM No.: <u>1304A</u>





702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9 Ph: (306) 653-6600 Fax: (306) 242-5599 <u>www.irdinc.com</u>







702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9 Ph: (306) 653-6600 Fax: (306) 242-5599 <u>www.irdinc.com</u>



Work Remaining: None

Schedule Include Estimate to Complete (on-track, ahead, behind):

Parts Used:

Pre-mature Equipment Failure:

Mileage / Travel Time: Total Travel: 4 hrs Total Onsite: 1 hrs

Safety Concerns:

Issues Related to Sub-Contractors:

Other Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		